Region 6 Sample Control Center, e-mail to warren.christy@epa.gov or to perez.myra@epa.gov

REQUEST FOR LABORATORY SAMPLE ANALYSES

Site Name: Falcon Refinery Superfund Site	City/State: Ingleside, Texas	CERCLIS #:TXD086278058	
GPRA Account #:	Site Spill ID #	Type of Investigation/Purpose: Remedial Investigation	
EPA SAM, RPM, OSC:	Analytical Turnaround Time	Type of Contract: RACS II	
Brian Mueller - RPM	Region 6 Lab: 35_X_	Contractor: : EA Engineering	
Mail Code: <u>6SF-RL</u>	CLP Organics: 7 14 21_X_ CLP Inorganics: 7 14 21 X_	Shipping Contact: Bob Owens	
Telephone #: 214-665-7167 Cell Phone # 214-392-1844	Are preliminary results required? 48 hrs VOA () Yes (X) No	Telephone #: 972-315-3922	
Fax #: 214-665-6660	72 hrs Extractables () Yes (X) No 72 hrs Inorganics () Yes (X) No	On Site Ph #:	
	(2010) Including duplication (1)	E-Mail address: rowens@eaest.com	
Potential Enforcement Action? (X) Yes () No	Requires justification and prior approval.	Date Sample Control Center Received Request For Sample Analysis:	
Proposed Sampling Period: 23 S	eptember 2013	Danks and equipment insales.	

Please assure that this request for analytical services has been signed and dated by the appropriate Site Assessment Manager, Remedial Project Manager, or On Scene Coordinator. Please assure that the Sample Control Center has a copy of all relevant Quality Assurance Project Plans (QAPPs) and Sampling and Analysis Plans (SAPs).

Is the QAPP, QASP, SAP, O&M Plan, GWMP,DAW, or other relevant plan being submitted with this Request For Sample Analyses? X Yes_ Previously Submitted

If no, please explain (expected date of submission etc.):

Signature of EPA Site Assessment Manager (SAM), Remedial Project Manager (RPM), or On Scene Coordinator (OSC) to signify approval of this analytical service request.

Signature:

Date: 7/16/13

9598250

1. General description of analytical services requested: (QA/R5 - Element B1)

Matrix	Analysis	Number of Samples	Field	d QC Samples
oonu@unoden		(without QC) high/low conc	How many?	Type?
Water	SOM01.2/Trace Water by SIM VOA	33 (including duplicates)		PA SAM PPM, GBC
Water	SOM01.2/Low Water by SIM SVOA	35 (including duplicates)		all Code 68F-RE
Water	ISM01.3/ICP-MS TAL Metals and Mercury (CVAA)	35 (including duplicates)	-7167 -1844	Slephone # 214-605 all Phone # 214-361
Water	ISM01.3/ICP-MS Dissolved Metals	35 (including duplicates)		

Additional description (areas where samples are being collected etc.):

Water samples from monitoring wells installed onsite will be sampled. Water samples will also include trip blanks and equipment rinsates.

2. Analytical protocol required (analytical method & method number, extraction or digestion method & method number, CLP SOW reference, for each matrix if required, etc.): (QA/R5 – Element B4)

Current CLP methods (08/28/12) are: Organics by SOM01.2, Inorganics by ISM01.3

Matrix	Analysis	Methods
Water	VOCs	SOM01.2/Trace Water by SIM
Water	SVOCs	SOM01.2/Low Water by SIM
Water	TAL Metals and Mercury	ISM01.3/ICP-MS
Water	Dissolved Metals	ISM01.3/ICP-MS

Additional Information:

Complete the following information if Method 5035 for VOA soils has been requested:

# of low conc. soils	# of medium conc. soils	Type of Vials	# of low conc. soils	# of medium conc. soils

3. CLP Modified Analysis Clause - The latest Statement of Works (SOWs), includes a modified analysis clause. The modified analysis allows the regions to request minor changes to current SOW analytical methods in order to meet specific field site requirements. The changes are limited in scope and must

be approved by the EPA CLP Program Manager and Contracting Officer before implementation. Information must be submitted <u>three weeks</u> prior to the sampling event. The information the client must submit three weeks prior to the sampling event are; Lab Request Form and the approved sampling plan/QAPP.

- 4. Analytical results required (specify laboratory documentation and reporting requirements, reporting units, format requirements, etc.): (QA/R5 Elements A6 and B4) <u>CLP analyses or EPA Houston laboratory</u>: Full data packages and EDDs according to protocols. PDF file is requested.
- Data requirements (reporting limits; per analyte per matrix; reporting units; applicable reference levels, etc.): (QA/R5 Elements A7, B1, and B4) (Attach extra pages if necessary) For CLP capabilities http://www.epa.gov/superfund/programs/clp/facts.htm. For Region 6 Laboratory capabilities http://www.epa.gov/earth1r6/6lab/r6lab.htm

Note: Samples submitted to the CLP for analysis must be low or medium concentration, single phase, homogenous (not oily), soil, sediment, or water. Also, samples with matrix related problems (oily material, high concentration of compounds, etc.) and/or high moisture content will raise the method CRQL's.

a. Compounds/chemicals of concern (Action levels etc.) – Required information – List the compounds/analytes driving the investigation and the action level required to meet DQO's.

water (µg/L)	soil (mg/kg)
designated yet Action	
	n levels required to meet DQOs for all dix A of the QAPP Addendum.
	e presented in Append

6. QC Requirements (PE samples & frequency, spikes, duplicates, blanks, & frequency)

QC Type	Frequency	QC Limits
MS/MD	1 per 20	
MS/MSD	1 per 20	

7. Data Review Options (For CLP generated data only)

Data review options apply only to data acquired through the CLP. See Attachment 5 (Region 6 Organic/Inorganic Data Review Options).

Data	turnaround	times	refer	to	calenda	r days
Data	turnaround	unico	10101	w	Carcillad	n unys.

Monk	tha	lavial	of	data	assessment	nood	ad	
Mark	the	ievei	OI	data	assessment	need	eu	١.

- ☐ Level 1 Modified CADRE (3 day turnaround)*
 - * Plus 1 5 days for processing and mailing.